

106/107 Digital Multimeters

Users Manual

June 2013, Rev. 2, 11/20 \odot 2013-2020 Fluke Corporation. All rights reserved. Specifications are subject to change without notice. All product names are trademarks of their respective companies.

106/107 Users Manual

Table 1 is a list of the symbols used on the Product and in this manual.

[]i	Consult user documentation.	⚠	WARNING. RISK OF DANGER.	
L	Static awareness. Static discharge can damage part(s).	Δ	WARNING. HAZARDOUS VOLTAGE. Risk of electric shock.	
~	AC (Alternating Current)	Ŧ	Earth	
	DC (Direct Current)	∔	Capacitance	
N	Both direct and alternating current	₩	Diode	
œ	Battery	Ф	Fuse	
CE	Conforms to European Union directives.			

Table 1. Symbols

Table 1. Symbols (cont.)

CATI	Measurement Category II is applicable to test and measuring circuits connected directly to utilization points (socket outlets and similar points) of the low-voltage MAINS installation.
САТШ	Measurement Category III is applicable to test and measuring circuits connected to the distribution part of the building's low-voltage MAINS installation.
САТ 🛙	Measurement Category IV is applicable to test and measuring circuits connected at the source of the building's low-voltage MAINS installation.
X	This product complies with the WEEE Directive marking requirements. The affixed label indicates that you must not discard this electrical/electronic product in domestic household waste. Product Category: With reference to the equipment types in the WEEE Directive Annex I, this product is classed as category 9 "Monitoring and Control Instrumentation" product. Do not dispose of this product as unsorted municipal waste.

Instrument Overview

Terminals

	A COM VQ-H-++ FUSED CAT II 1 2 3 bhc01.jpg
Item	Description
(1)	Input terminal for ac and dc current measurements to 10 A and current frequency (107 only) measurements.
2	Common (return) terminal for all measurements.
3	Input terminal for voltage, resistance, continuity, diode (107 only), capacitance, and frequency (107 only) measurements.

Display

Figure 1 and Table 2 show the items on the Product display.




Figure 1. Display

Table	2.	Disp	olay
-------	----	------	------

Item	Description	Item	Description
1	High voltage	8	Frequency is selected
2	Display Hold is enabled	9	Farads
3	Continuity selected	10	Millivolts
4	Diode test is selected	(1)	Amps or volts
5	Duty Cycle is selected	(12)	Dc or ac voltage or current
6	Decimal prefix	(13)	Auto Range mode is enabled
7	Ohms is selected	(14)	Low battery. Replace battery.

Auto Power Off

The Product automatically powers off after 20 minutes of inactivity.

To restart the Product, turn the rotary switch back to the **OFF** position and then to a necessary position.

To disable the Auto Power Off function, hold down the **YELLOW** button when turning on the Product, until P_0FF shows on the display.

Auto Backlight Off

The backlight automatically turns off after 2 minutes of inactivity.

To disable the Auto Backlight Off function, hold down \circledast when turning on the Product, until LoFF shows on the display.

Note

To disable both the Auto Power Off function and the Auto Backlight Off function, hold down the **YELLOW** button and (at the same time, until both PoFF and LoFF show on the display.

Measurements

Data Hold

▲▲ Warning

To prevent possible electrical shock, fire or personal injury, do not use the HOLD function to measure unknown potentials. When HOLD is turned on, the display does not change when a different potential is measured.

To hold the present reading, push [HOLD]. Push [HOLD] again to continue normal operation.

Measure AC and DC Voltage

To measure ac and dc voltage:

- 1. Choose ac or dc by turning the rotary switch to \tilde{v} or \overline{v} .
- Connect the red test lead to the VΩ-I → terminal and the black test lead to the COM terminal.
- 3. Measure the voltage by touching the probes to the correct test points of the circuit.
- 4. Read the measured voltage on the display.

Digital Multimeters

Measurements




Figure 2. Measure AC and DC Voltage

Measure AC or DC Current

<u>∧</u>∧ Warning

To prevent possible electrical shock, fire, or personal injury, remove circuit power before you connect the Product in the circuit when you measure current. Connect the Product in series with the circuit.

- 1. Turn the rotary switch to $\widetilde{\underline{A}}$.
- 2. Push the **YELLOW** button to toggle between ac or dc current measurement.
- 3. Connect the red test lead to the **A** terminal to be measured and connect the black test lead to the **COM** terminal.
- 4. Break the circuit path to be measured.
- 5. Connect the test leads across the break and apply power.
- 6. Read the measured current on the display.




Figure 3. Measure AC and DC Current

Measure Resistance

- Turn the rotary switch to [™]_n[→] (106 does not have →). Make sure power is disconnected from the circuit to be measured.
- Connect the red test lead to the VΩ-I← → terminal and the black test lead to the COM terminal.
- 3. Measure the resistance by touching the probes to the desired test points of the circuit.
- 4. Read the measured resistance on the display.

Test for Continuity

With the resistance mode selected, push the **YELLOW** button once to activate the continuity mode. If the resistance is <70 Ω , the beeper sounds continuously, designating a short circuit. If the Product reads []L, the circuit is open.

Digital Multimeters Measurements




Figure 4. Measure Resistance/Continuity

Maintenance

Beyond replacing the batteries and fuse, do not attempt to repair or service the Product unless you are qualified to do so and have the relevant calibration, performance test, and service instructions. The recommended calibration cycle is 12 months.

<u>∧</u>∧ Warning

To prevent possible electrical shock, fire, or personal injury:

- Remove the input signals before you clean the Product.
- Use only specified replacement parts.
- Use only specified replacement fuses.
- Have an approved technician repair the Product.

For safe operation and maintenance of the Product, repair the Product before use if the batteries leak.

General Maintenance

Periodically wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents. Dirt or moisture in the terminals can affect readings.

To clean the terminals:

- 1. Turn the Product off and remove the test leads.
- 2. Shake out any dirt that may be in the terminals.
- 3. Soak a new swab with isopropyl alcohol and work around the inside of each input terminal.
- 4. Use a new swab to apply a light coat of fine machine oil to the inside of each terminal.

Test the Fuse

- 1. Turn the rotary switch to $\frac{\sqrt{1}}{\Omega^2}$ (106 does not have \Rightarrow).
- 2. Plug a test lead into the $V\Omega + \rightarrow$ terminal and touch the probe to the A terminal.
 - A good A terminal fuse is indicated by a reading less than 0.5 Ω.
 - If the display reads IL, replace the fuse and test again.
 - If the display shows any other value, have the Product serviced. See Service and Parts.

Replace Batteries and the Fuse

To replace the batteries or the fuse, see Figure 5.

A 🛵 Caution

Be sure to observe Electro Static Discharge precautions.

Digital Multimeters Maintenance




Figure 5. Replace Batteries and the Fuse

Service and Parts

If the Product fails, first check the batteries and fuse. Then, review this manual to make sure you are operating the Product correctly.

Replacement parts are:

Item	Fluke Part Number		
Batteries	2838018		
Battery door	4319659		
Test leads TL175	4306653		
Fuse	803293		
Screws	4320657		

General Specifications

Maximum voltage between any terminal and Earth Ground	600 V
Fuse protection for A input	11 A, 1000 V, IR 17 kA
Display (LCD)	6000 counts, updates 3/sec
Battery Type	2 AAA, NEDA 24A, IEC LR03
Battery Life	200 hours minimum
Temperature	
Operating	0 °C to 40 °C
Storage	30 °C to 60 °C
Relative Humidity	
Operating Humidity	Non-condensing when <10 °C; ≤90 % at 10 °C to 30 °C; ≤75 % at 30 °C to 40 °C
Operating Humidity, 40 MΩ Range	≤80 % at 10 °C to 30 °C; ≤70 % at 30 °C to 40 °C
Altitude	
Operating	2000 m
Storage	12,000 m

106/107 Users Manual

Temperature Coefficient	0.1 X (specified accuracy) / °C (<18 °C or >28 °C)
Size (HxWxL)	142 mm x 69 mm x 28 mm
Weight	
IP Rating	IEC 60529: IP 40
Safety	
General	IEC 61010-1: Pollution Degree 2
Measurement	IEC 61010-2-033: CAT III 600 V
Electromagnetic Compatibility (EMC)	
International	IEC 61326-1: Portable, IEC 61326-2-2

Group 1: Equipment has intentionally generated and/or uses conductively-coupled radio frequency energy that is necessary for the internal function of the equipment itself.

CISPR 11: Group 1, Class A

Class A: Equipment is suitable for use in all establishments other than domestic and those directly connected to a low-voltage power supply network that supplies buildings used for domestic purposes. There may be potential difficulties in ensuring electromagnetic compatibility in other environments due to conducted and radiated disturbances.

Emissions that exceed the levels required by CISPR 11 can occur when the equipment is connected to a test object. The equipment may not meet the immunity requirements of this standard when test leads and/or test probes are connected.

Korea (KCC)..... Class A Equipment (Industrial Broadcasting & Communication Equipment)

Class A: Equipment meets requirements for industrial electromagnetic wave equipment and the seller or user should take notice of it. This equipment is intended for use in business environments and not to be used in homes.

Accuracy Specifications

Accuracy is specified for 1 year after calibration, at operating temperatures of 18 °C to 28 °C, relative humidity at 0 % to 75 %. Accuracy specifications take the form of: $\pm([\% \text{ of Reading}] + [Number of Least Significant Digits]).$

Function	Benne	Resolution	Accuracy		
Function	Range	Resolution	106	107	
AC Volts (40 Hz to 500 Hz) ^[1] V	6.000 V 60.00 V 600.0 V	0.001 V 0.01 V 0.1 V	1.0 % + 3	1.0 % + 3	
DC Volts	6.000 V 60.00 V 600.0 V	0.001 V 0.01 V 0.1 V	0.5 % + 3	0.5 % + 3	
AC Millivolts mV	600.0 mV	0.1 mV	3.0 % + 3	3.0 % + 3	
Diode Test ^[2] ➡	2.000 V	0.001 V	N/A	10 %	
 All AC, Hz, and duty cycle are specified from 1 % to 100 % of range. Inputs below 1 % of range are not specified. Typically, open circuit test voltage is 2.0 V and short circuit current is <0.6 mA. 					

Digital Multimeters Accuracy Specifications

Function	B	Devel the	Accuracy		
Function	Range Resolution -		106	107	
	400.0 Ω	0.1 Ω	0.5 % + 3	0.5 % + 3	
Resistance	4.000 kΩ 40.00 kΩ	0.001 kΩ 0.01 kΩ	0.5 % + 2 0.5 % + 2	0.5 % + 2 0.5 % + 2	
Ω	400.0 kΩ	0.1 kΩ	0.5 % + 2	0.5 % + 2	
	4.000 MΩ 40.00 MΩ	0.001 MΩ 0.01 MΩ	0.5 % + 2 1.5 % + 3	0.5 % + 2 1.5 % + 3	
	50.00 nF 500.0 nF	0.01 nF 0.1 nF	2 % + 5 2 % + 5	2 % + 5 2 % + 5	
Capacitance [1]	5.000 μF	0.001 μF	5 % + 5	5 % + 5	
-++-	50.00 μF	0.01 μF	5 % + 5	5 % + 5	
	500.0 μF 1000 μF	0.1 μF 1 μF	5 % + 5 5 % + 5	5 % + 5 5 % + 5	

Damas	Deschution	Accuracy	
Range Resolution		106	107
50.00 Hz	0.01 Hz		
500.0 Hz	0.1 Hz		
5.000 kHz	0.001 kHz	NA	0.1 % + 3
50.00 kHz	0.01 kHz		
100.0 kHz	0.1 kHz		
1 % to 99 %	0.1 %	NA	1 % typical [3]
	500.0 Hz 5.000 kHz 50.00 kHz 100.0 kHz	50.00 Hz 0.01 Hz 500.0 Hz 0.1 Hz 500.0 kHz 0.001 kHz 50.00 kHz 0.01 kHz 50.00 kHz 0.01 kHz 100.0 kHz 0.1 kHz	Range Resolution 106 50.00 Hz 0.01 Hz 106 500.0 Hz 0.1 Hz 1000000000000000000000000000000000000

 Specifications do not include errors due to test lead capacitance and capacitance floor (may be up to 1.5 nF in the 50 nF range).

[2] All AC, Hz, and duty cycle readings are specified from 1 % to 100 % of range. Inputs below 1 % of range are not specified.

[3] Typical means when the frequency is at 50 Hz or 60 Hz and the duty cycle is between 10 % and 90 %.

Function	Range	Resolution	Accuracy		
Function			106	107	
AC Current (40 Hz to 200 Hz) Ã ^[1]	4.000 A 10.00 A	0.001 A 0.01 A	1.5 % + 3	1.5 % + 3	
DC Current	4.000 A 10.00 A	0.001 A 0.01 A	1.5 % + 3	1.5 % + 3	
[1] 10 A duty cycle <7 minutes on, 20 minutes off, 25 °C to 40 °C.					

Function	Overload Protection	Input Impedance (Nominal)	Common Mode Rejection Ratio	Normal Mode Rejection Ratio
AC Volts	600 V ^[1]	>10 M Ω <100 pF ^[2]	>60 dB at dc, 50 Hz or 60 Hz	-
AC Millivolts	600 mV	>1 M, <100 pF	>80 dB at dc, 50 Hz or 60 Hz	_
DC Volts	600 V ^[1]	>10 MΩ <100 pF	>100 dB at 50 Hz or 60 Hz	>60 dB at 50 Hz or 60 Hz
[1] 6 x 10 ⁵ V Hz Max.				

[2] For mV (AC), input impedance is approximately 1 MΩ.